

BR 05

Schnellzug-

Schleppenderlok

2200

2215


2201

2216

www.arnold-ersatzteile.de


CTN MUC

2270-35



2215-001 2201-001/3010

2216-001 2200-001/3010




2215-002



2215-31



2215-003



2215-11

2215-004

2200-004

2216-002

2276-75

2460-70




2215-005

OEL





2215-79



2215-006




0224-80



ARNOLD

BR 05

Schnellzug- 2200 2215
Schleptenderlok 2201 2216



2215-36

2215-014
2200-014
2201-014
2215-32



0221-4



2215-016



2215-015
2200-022

2022-80
2545-56 0441-4
0222-8/9

0736-75


2275-45

2215-70



2215-017


Kohlewechsel
Replacing carbon brushes
Changement des balais



0100-29

0100-75

Haftreifenwechsel
Changing traction tires
Echange des bandages anti-dérapants



0221-52